



Pre-Warranty Inspection Report

Administrator:	Inspection #	104821			
Customer Name:	Email Address:				
Vehicle Location Information:					
	Facility Phone				
Jupiter, FI 33458	Facility Contact:				
Reason For Inspection: Pre-purchase inspection Test drive the vehicle at least 10 miles. Be sure to take					
before and after ODOMETER pictures. Fax this worksheet ASAP. Upload Photos the evening of the inspection.					

******CALL THE OWNER PRIOR TO GOING TO SET UP THE APPOINTMENT FOR INSPECTION._FAX REPORT TO 706-955-0029 or 706-451-0390 ASAP!!!! UPLOAD PICTURES TO WEBSITE (http://www.carinspector.us)

THE EVENING OF THE INSPECTION. NO EXCEPTIONS!!!

Verbal Given To:			Inspected By: CT		СТ	
Date Inspected: 10-11-10			Time Inspected:		11:04	
Yr/Mk/Mdl: 2003 Land Rover Range Rover		Mileage before test drive: 76811		after: 76820		
VIN:	SALMF	11473A135040	Production Date:		03-03	
Engine Size: 4.4		Fuel Type:		GAS		
Transmission Type: AUTO		Drive Type:		AWD		
Oil Level: FULL		Oil Condition:		GOOD		
Coolant Level: FULL		Coolant Condition:		GOOD		
Trans Level: SEALED		Trans Condition:		NA		
Front Diff Level: NA		Front Diff Condition:		NA		
Rear Diff Level:	Rear Diff Level: NA		Rear Diff Condition:		NA	
Transfer Case Level: NA		Transfer Case Condition:		NA		
Power Steering Level: FULL		Power Steering Condition: GOOD		GOOD		
Brake Fluid Level: FULL		Brake Fluid Condition:		GOOD		
Belts:	Hoses:	Overall Condition:	Abuse?	Mods?	Overheat?	
GOOD	GOOD	FAIR	NO	NO	NO	
Lack of Lube?	Previous or Current	Towing Type?	Tires Factory Size?	Mechanical Failures?	Service History?	
NO	Collision?	EQUIP	YES	NO	110	
	NA					
Service	Prior	License Plate Info:	Level of Teardown:			
Stickers?	Commercial	TEMP	FULLY ASSEMBLED			
NO	Usage? NO					

Vehicle owner signature:

IMPORTANT NOTICE:

The sole purpose of this inspection report is to assist the warranty company in evaluating the eligibility of the vehicle described herein for mechanical breakdown coverage. This inspection report may be relied upon only by the warranty company, and neither the warranty company, the inspector, nor the inspection company will have any liability relating to this inspection. This is not a safety inspection, and no conclusions may be drawn as to the safety of the vehicle from either the inspection results or from the warranty company's decision to issue mechanical breakdown coverage. Completion of this inspection does not mean that mechanical breakdown coverage will be provided, and the coverage may not include all inspected parts. This inspection was performed by CarInspector.US (CIU) in a professional manner, without the use of diagnostic tools or equipment. Accordingly, CIU, is not liable for any hidden, latent, or undetected conditions or defects on the vehicle or any of its component parts. This inspection does not create or result in any representations or warranties by CIU with respect to the safety, condition, or operation of the vehicle or any of its parts. CIU expressly disclaims any such representation and warranties.

CarInspector.US representative sig	nature:	Date:
our mopeotories representative eng		2 0.10.

INTERIOR DESCRIPTION REPLACE **EXTERIOR** REPLACE REPAIR REPAIR **BODY BODY** DESCRIPTION ITEM ITEM OK OK Seat Belts \boxtimes Brake Lamps \boxtimes Keyless Entry Key fob(alarm) inop Parking Lamps \boxtimes \boxtimes Anti-Theft Interior Lights Radio Operation \boxtimes Head Lamps X Power Windows Back Up Lamps Power Locks Turn Signals Power Mirrors Windshield Wipers Power Seats Jack/Tire Tools \boxtimes Power Sunroof Frame/Unibody \boxtimes \boxtimes 12/32 ☐ Tires: Front-Left Horn 12/32 Front-Right Hood Release \boxtimes \boxtimes \boxtimes Rear-Left \boxtimes 12/32 Trunk Release 12/32 Fuel Door Release Rear-Right \boxtimes \boxtimes 12/32 Windshield Washer \boxtimes Spare \boxtimes MECHANICAL Good Fair Poor Needs Needs Yes/No Comments **ITEMS** Service Replacement Engine: Evidence of Leaks Right valve cover gasket Abnormal Noises Performance Fuel Lines/Hoses X Water Pump Condition Radiator \boxtimes X Battery & Terminals **Engine Mounts** \boxtimes X Exhaust System Starter Operation Transmission: Evidence of Leaks Abnormal Noises M Performance Clutch Performance Steering and Suspension: \boxtimes Evidence of Leaks Abnormal Noises Performance Shocks/Struts Brakes: Evidence of Leaks Abnormal Noises Performance \boxtimes Brake Lines/Hoses \boxtimes Brake Pads/Shoes Air Conditioning: Evidence of Leaks Abnormal Noises Performance X Drivetrain: Evidence of Leaks \boxtimes Abnormal Noises Performance

Pre-Warranty Inspection # 104821

Axle Boots

Page 2 of 2

























